


Measure technology problem--how to calibration?


How to calibration?

The way to calibration


1, Calibration: select pixel, 100%, max resolution



2, Click on the "option" to select "calibration"



3, Calibration: Magnification, Actual Length, Meter



4, After select "calibration", choose the unit and multiplying power you need, then you can calibrate.

How to set cross hair on HAYEAR measure software?

First step: select setup

Second step: select video overlay

Third step: select the Cross in Type

